QUALITY CONTROL

BR No: 18/13-14 dt: 30/04/2013

Name of the Work: Providing Cement Concrete to Cross Roads @ back side of Badushitte Hotel in W.No.13 in Shettyhalli Sub-division

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT&H at this stage is not feasible since this work was executed 2 years back.

Assistant Executive Engineer
Shetty Halli Sub Division
Bruhat Bengaluru Mahanagara Palike

Executive Engineer
Dasarahalli Division, Dasarahalli Zone
Bruhat Bengaluru Mahanagara Palike

ROAD HISTORY

BR No: 18/13-14 dt: 30/04/2013

Name of the Work: providing Cement Concrete to Goods Roads @ Backside of Bedurhilton Hotel. in W.No-13 in Shettyhalli Subdivision

Due to frequent delimitation of ward's the roads in this ward are bifurcated and distributed among different wards, Hence History of these/this road could not be maintained. Now road History is being uploaded to GIS and will be maintained regularly.

Assistant Executive Engineer
Shetty Halli Sub Division
Bruhat Bengaluru Mahanagara Palike

Executive Engineer
Dasarahalli Division, Dasarahalli Zone
Bruhat Bengaluru Mahanagara Palike